



IFW

Dr. Ing. Giok Djien Go
Pöhlgrabenstr. 45
D-65510 Idstein
Germany

phone/fax +49 6126 8949

Registered

Mrs. Deanne L. Draper
USPTO
Art Unit 3616

My submittal of amended appls regarding ~~09/554,463~~, ~~10/690,741~~ and 10/690,742
Docket Nos.: ~~G6A2~~, ~~G6A3~~ and G6A4

Dear Mrs. Draper

2004-08-31

Please replace the pages due to the following error:

In the NHSTA side crash test, which, currently legislated, idealizes an SUV crashing at an angle of 30° into a door or vehicle side.

the buckle assembly, actuator and other parts are destroyed
changed into

As a result, the buckle assembly, actuator and other parts are destroyed.

I apologize for the inconvenience resulting therefrom.

Thank you for your attention and help in advance.

Kind regards

Go

Go Giok Djien

Attached

Dr. Ing. Giok Djien Go
Pöhlgrabenstr. 45
D-65510 Idstein
Germany